

Protective Coatings - Electronic Management System

Manage the status of Protective Coatings

IMAP's Protective Coatings Management System Encompasses a complete inventory and condition of your facility's assets from equipment and piping to buildings and structures

- Evaluates the condition of the coatings and lining systems
- Identifies potential for CUI
- Associates Plot Plans
 - Floor Plans
 - P&ID's
 - Geo Tag Images
- Prioritizes Repair

You're Covered with
IMAP Software

Standardized audit results provide consistency in reporting and response

Assessment is measured against industry standards integrated into the software and prioritized based on maintenance policy and existing condition

Standards Ensure Compliance

Results in the field are matched with corporate policy, industry standards and best practices

Identifies Costs

Know the cost of repair and upgrades including access, material and labour

Budget and Planning

See the total impact on your bottom line, plan maintenance activity based on priorities and budgets

Information at Your Fingertips

Secure cross browser access 24/7 on any System or Mobile Device

User Driven Custom Report Builder

Unprecedented control over report generation with check boxes & drag and drop report builder



Who Benefits?

Engineering • Planning
Operations • Maintenance
Industrial Hygiene • Reliability
Health & Safety
Third Party Contractors

Contact Us

IMAP Audits Inc.
402B 546 Christina St N
Sarnia, ON N7T 5W6
519-312-5453
software@imapaudits.com

Individual Equipment Report - Coatings

Equip. ID #:	BA-1001 B	Equip. Group:	Ref. #:
Plant/Unit:	Crude/VAC	Area:	IA-01
Location:	Crude Unit	Material:	A 263 C
		Service:	Type:
		Operating Temp.:	103
Description: Crude Heater			
Observation No.:	PCD 864-3707	Audit Date:	20-Dec-2004
		Audit Cycle:	20-Dec-2005
		Shutdown:	No
		Service Code:	PSG2
		Reason Code:	PRG8
		Priority Code:	Class 1
Comments: The exposed heater has staining, a worn out coating, mechanical damage and heavy soot corrosion present. The ladders, kick plates and rails have a worn out coating. There is heavy corrosion on the pipe brackets and a worn out coating. There is heavy corrosion on the West end. The duct work has a worn out coating. A complete new coating system is required.			
			
IMAP		Caution: Gaskets may contain asbestos. 20-Dec-2012 3:23:46 PM Page 24	



Software as a service costs

\$40.00⁺ per mo.