

Fireproofing - Electronic Management System

Manage your Fireproofing

From Identification to Repair

You're Protected with
IMAP Software

IMAP's Fireproofing Management System Encompasses a complete inventory and condition of your facility's assets from equipment and piping to buildings and structures

- Identifies existing fireproofing materials
- Condition
- manufacturers recommended practices
- insurance requirements
- Associates Plot Plans
 - Floor Plans
 - Detailed Description
 - Geo Tag Images

Standardized audit results provide consistency in reporting and for decision making

Assessment is measured against industry standards integrated into the software and prioritized based on maintenance policy and existing condition

Standards Ensure Compliance

Results in the field are matched with corporate policy, industry standards and best practices

Identifies Costs

Know the cost of repair and upgrades including access, material and labour

Budget and Planning

See the total impact on your bottom line. Plan maintenance activity based on priorities and budgets

Information at Your Fingertips

Secure cross browser access 24/7 on any System or Mobile Device

User Driven Custom Report Builder

Unprecedented control over report generation with check boxes & drag and drop report builder

Who Benefits?

*Engineering • Planning
Operations • Maintenance
Industrial Hygiene • Reliability
Health & Safety
Third Party Contractors*


Petro Chemical ∞ **Oil & Gas**
Pulp and Paper ∞ **Mining**
Manufacturing ∞ **Power**

Integrates with your existing ERP

Individual Equipment Report - Fireproofing

Equip. ID #:	Equip. Group:	Structural Steel	Ref. #:
1ES-SS-EA-1301			
Plant/Unit:	Crude/VAC	Area:	IA-01
Location:	Crude Unit	Material:	Carbon Steel
		Service:	Out of Service
		Type:	Operating Temp.: 0
Description: Equipment Structure - Structural Steel Supporting EA-1301, EA-1302, EA-1303, located south of DA-1302			
Observation No:	Audit Date	Audit Cycle	Shutdown
FPC 3769-4145	25-Feb-2008	25-Feb-2009	No
		Service Code	Reason Code
		ISC(S)	IRC(C)
			Priority Code
			Class 1

Comments:
The equipment structure supporting EA-1307, EA-1302 and EA-1303 is currently fireproofed with pyrocrete. There is a major breakdown occurring on the horizontal beams and the vertical columns. Recommend a further destructive audit by the Reliability Department to determine if corrosion exists. There is approximately 200 sq ft of pyrocrete present on this structure. Scaffolding is required. Refer to images a and b. Refer to plot plan #D-10010-B for location.



IMAP **Caution: Gaskets may contain asbestos.**
22-Jan-2013 8:38:57 AM Page 1

Software as a service costs

\$40.00+ per mo.

Contact Us

IMAP Audits Inc.
402B 546 Christina St N
Sarnia, ON N7T 5W6
519-312-5453
software@imapaudits.com